



Address: 6F., No. 58, Ln 188, Ruey Kuang Rd, Neihu, Taipei
Tel: +886-2-6606-8877
Fax: +886-2-6606-8879

Radiated Emission Measurement

Operator: Rick

File :3

Data :#4


Date: 2019/8/12

Temperature: 24 °C

-20.0 dBm

Time: 下午 09:13:15

Humidity: 60 %



Site : Chamber

Condition : ETSI EN300_328-RX_Spurious_N

EUT : W6M21906-19111

M/N:

Test Mode : RX CH39

Note :

Polarization: **Vertical**

Power : 230Va.c.

Distance: 3m

Mk.	Frequency (MHz)	Reading (dBm)	Detector	Corr. factor (dB)	Result (dBm)	Limit (dBm)	Ant.Pos (cm)	Tab.Pos (deg.)	Margin (dB)	Comment
*	2412.826	-58.45	peak	-1.71	-60.16	-47.00	150	320	-13.16	
	3470.942	-63.44	peak	0.72	-62.72	-47.00	150	120	-15.72	

*:Maximum data x:Over limit !:over margin



Address: 6F., No. 58, Ln 188, Ruey Kuang Rd, NeiHu, Taipei
Tel: +886-2-6606-8877
Fax: +886-2-6606-8879

Radiated Emission Measurement

Operator: Rick

File : 3

Data : #2


Date: 2019/8/12

Temperature: 24 °C

-20.0 dBm

Time: 下午 09:10:15

Humidity: 60 %



Site : Chamber

Condition : ETSI EN300_328-RX_Spurious_N

EUT : W6M21906-19111

M/N:

Test Mode : RX CH39

Note :

Polarization: *Horizontal*

Power : 230Va.c.

Distance: 3m

Mk.	Frequency (MHz)	Reading (dBm)	Detector	Corr. factor (dB)	Result (dBm)	Limit (dBm)	Ant.Pos (cm)	Tab.Pos (deg.)	Margin (dB)	Comment
-----	-----------------	---------------	----------	-------------------	--------------	-------------	--------------	----------------	-------------	---------

*:Maximum data x:Over limit !:over margin



Address: 6F., No. 58, Ln 188, Ruey Kuang Rd, NeiHu, Taipei
Tel: +886-2-6606-8877
Fax: +886-2-6606-8879

Radiated Emission Measurement

Operator: Rick

File : 3

Data : #5


Date: 2019/8/12

Temperature: 24 °C

-20.0 dBm

Time: 下午 09:26:51

Humidity: 60 %



Site : Chamber

Condition : ETSI EN300_328-RX_Spurious_N

EUT : W6M21906-19111

M/N:

Test Mode : RX CH39

Note :

Polarization: *Vertical*

Power : 230Va.c.

Distance: 3m

Mk.	Frequency (MHz)	Reading (dBm)	Detector	Corr. factor (dB)	Result (dBm)	Limit (dBm)	Ant.Pos (cm)	Tab.Pos (deg.)	Margin (dB)	Comment
-----	-----------------	---------------	----------	-------------------	--------------	-------------	--------------	----------------	-------------	---------

*:Maximum data x:Over limit !:over margin



Address: 6F., No. 58, Ln 188, Ruey Kuang Rd, NeiHu, Taipei
Tel: +886-2-6606-8877
Fax: +886-2-6606-8879

Radiated Emission Measurement

Operator: Rick

File : 3

Data : #3


Date: 2019/8/12

Temperature: 24 °C

-20.0 dBm

Time: 下午 09:11:21

Humidity: 60 %



Site : Chamber

Condition : ETSI EN300_328-RX_Spurious_N

EUT : W6M21906-19111

M/N:

Test Mode : RX CH39

Note :

Polarization: *Horizontal*

Power : 230Va.c.

Distance: 3m

Mk.	Frequency (MHz)	Reading (dBm)	Detector	Corr. factor (dB)	Result (dBm)	Limit (dBm)	Ant.Pos (cm)	Tab.Pos (deg.)	Margin (dB)	Comment
-----	-----------------	---------------	----------	-------------------	--------------	-------------	--------------	----------------	-------------	---------

*:Maximum data x:Over limit !:over margin



Address: 6F., No. 58, Ln 188, Ruey Kuang Rd, NeiHu, Taipei
Tel: +886-2-6606-8877
Fax: +886-2-6606-8879

Radiated Emission Measurement

Operator: Rick

File : 3

Data : #6


Date: 2019/8/12

Temperature: 24 °C

-20.0 dBm

Time: 下午 09:27:59

Humidity: 60 %



Site : Chamber

Condition : ETSI EN300_328-RX_Spurious_N

EUT : W6M21906-19111

M/N:

Test Mode : RX CH39

Note :

Polarization: *Vertical*

Power : 230Va.c.

Distance: 3m

Mk.	Frequency (MHz)	Reading (dBm)	Detector	Corr. factor (dB)	Result (dBm)	Limit (dBm)	Ant.Pos (cm)	Tab.Pos (deg.)	Margin (dB)	Comment
-----	-----------------	---------------	----------	-------------------	--------------	-------------	--------------	----------------	-------------	---------

*:Maximum data x:Over limit !:over margin